
HERMES Logi
2K2
120
+Vcc
Battery
470
CS
ROM
RAM
Vcc
Drive
Z80
A15
MREQ
RESET
WAIT
HALT
INT
CLK
4MHz
A2
A3
A4
IOREQ
A5
A6
A7
NMI
WR
RD
138
CS0-3
INT
PPI2
PPI3
Drivers
PPI0
(Ctrol:3)
(Pwr & Comm. RxTx)
PA
PB
PC
RESET
LEDS
C
D
E2-4
E0-3
COMM
DATA
Tx
Rx
GND
2K2
244
SW
PPI1
(Hex Key Display)
top View
GND
+Vcc
OUT
4016
Vcc
00
138
30
NC

HERMES (CONTROL)



SW	@ add	
0	1112 0450	LEVEL 0 Diagnostics
1	1346 0542	CTROL KEYS Hex. Programing
2	1624 0658	DEONTOS Comand Pgm
3		
4		
5		
6		
7		

HERMES Drive





EXTERNAL PORTS

Port	PPI (4)	(5)	(6)	(7)
A	16	20	24	28
B	17	21	25	29
C	18	22	26	30
ctrl	19	23	27	31



A-D & DA CONVERTERS



KEY BOARD DISPLAY





/CONECTION/



HERMES (Ports)













SCANER & WAVE GEVERATOR

6A 10/94

Ⓐ = TIMER

Ⓑ = SCAN

Port	Use
E4	[T.Time-] 30 Hz
E5	301 (w) (61)
E6	302 (w2) (62)
E7	IT (CW)
E8	300 (w0)
E9	301 (w1)
EA	302 (w2)
EB	IT (CW)
EC	100 (w0)
ED	101 (w1)
EE	102 (w2)
EF	IT (CW)
F0	Data
F1	Ctrol
F2	ctrol (Fin)
F3	PPI (CW)

RELOJ · B · A · [T.Time] · OSC · CLK · RD · ENABLE · INT · GEN · FIN · CK

OSC · SCAN · RD · WT · CLR · ADC808Y · ADC/FLASH · I_{OV} · FIN · ARRANQUE

V_{IN} · V_0 … V_{15} · MUX

V_{OUT} · GND · PDo - PD2

BEEP = PC2

TIMER · SCAN · END

FLASH · CLK · ENABLE · RD · INT · CE2 · CE1 · HM7683 · PDo-2 · OP

Port	PB	Use
8L	47	SCAN (IT) (CW)
	48	SCAN (OSC) (300 Hz)
	49	SCAN (ADC) (10 Hz)
A1	3A	READ (ADC) (3A, 3B)
	3B	GEN (IT) (CW)
	3C	WRITE (ADC) 1 Hz

PDo-2 · [T.Time] (300 Hz) · [T.Time] · PPI · PA · PB · PC · RELOJ · A · B · OSC · ENABLE · GEN · ARRANQUE · FIN · BEEP







74LS139



7400



74LS00



74LS32



74LS393





74LS30









74LS27



8255



74LS245

PORTS Map

@	HEX		
ØØØ	ØØ	PW 5A 2.5 - 30V.. (ØØ - 7F) Pw. Supply A	OUT
ØØ1	Ø1	Rx - Tx DATA	IN / OUT
ØØ2	Ø2	Rx - Tx FLAGS // Switches // Leds	IN / OUT
ØØ3	Ø3	C.W.	IN
ØØ4	Ø4	Display Segment	OUT
ØØ5	Ø5	Display Digit	OUT
ØØ6	Ø6	Keyboard & Display	IN / OUT
ØØ7	Ø7	C.W.	IN
ØØ8	Ø8	A PW	OUT
ØØ9	Ø9	B DRIVERS 1	OUT
Ø1Ø	ØA	C	OUT
Ø11	ØB	C.W.	IN
Ø12	ØC	A PW	OUT
Ø13	ØD	B DRIVERS 2	OUT
Ø14	ØE	C	OUT
Ø15	ØF	C.W	IN
Ø16	1Ø	A LOGIC	IN / OUT
Ø17	11	B IN - OUT 1	IN / OUT
Ø18	12	C	IN / OUT
Ø19	13	C.W.	IN
Ø20	14	A LOGIC	IN / OUT
Ø21	15	B IN - OUT 2	IN / OUT
Ø22	16	C	IN / OUT
Ø23	17	C.W.	IN
Ø24	18	A LOGIC	IN / OUT
Ø25	19	B IN - OUT 3	IN / OUT
Ø26	1A	C	IN / OUT
Ø27	1B	C.W.	IN
Ø28	1C	PW 2A 2.5 - 30 Vcc (80 - FF) PW Supply 2	OUT
Ø29	1D	PW 2A 2.5 - 30 Vcc (80 - FF) PW Supply 1	OUT
Ø3Ø	1E	A/D Channel Select (8) (ØØØØ1ØØØ) 1= Enable	OUT
Ø31	1F	C.W.	IN

248	F8	NC	240	FØ	Data (Interf.	E8	2Ø1	EØ	
249	F9	NC	241	F1	CTrol	E9	2Ø2	E1	
25Ø	FA	NC	242	F2	Fin	EA	2Ø3	E2	Comf
251	FB	NC	243	F3	cw PPI	EB	ITcw	E3	Ø/1
252	FC	A/D Converter	244	F4		EC	1Ø1	E4	3ØØ
253	FD	A/D Converter	245	F5	Conf.	ED	1Ø2	E5	3Ø1
254	FE	A/D Converter	246	F6	Ø/1	EE	1Ø3	E6	3Ø2
255	FF	A/D Converter	247	F7		EF	ITcw	E7	ITcw





DRIVERS



D0 - D7 ⟺ PC (Port 88Z)

D0 - D2 ⟺ SPECTRUM

COMUNICACIONES

(Front Side)



(MALE)



PPI



(MALE) RELE & OPTO BOARD



RELE & OPTO

OPTO

RELES

ROM MAP

ØØØ	ØØØØ	INITIAL RESET	
Ø72	ØØ48	VIN RUTINE	
1117	Ø45D	LEVEL Ø	Ø
1346	Ø542	CTROL KEYS	1
1624	0658	MAIN PGM	2
1564	061C	CHECK IN RUTINE (C.M)	
	2ØØØ	READ BLOCK 27C512	
	2Ø31	WRITE BLOCK "	
	2ØCF	Verifie CLEAR "	
	2ØA4	Read ROM Add "	
	2ØBD	Read Block 27C256	
	2ØF2	WRITE BLOCK "	
	2131	Read Add ROM "	
	2148	COPY RUTINE	
	215A	CLEAR RAM Buffer	

Dionisos

RAM MAP

32768	8000	DELAY "CTE"	L
69	01		H
32770	8002	DELAY "HL"	L
71	03		H
32772	8004	(8)	
73	05	(7)	
74	06	(6)	
75	07	(5)	
76	08	(4)	
77	09	(3)	
78	0A	(2)	
79	0B	(1)	
80	0C	(0)	
32781	800D	KEY CODE PULSED	
32782	800E	VALUE DATA Enter	
32783	800F	VALUE Add. Enter	L
84	10		H
32785	8011	Key Code Convert	
32786	8012	Rutine 2-4 Key : 2-Ø	
32787	8013	Add Messaje Display	L
88	14		H
32789	8015	RESULT 255 = Si Ø = No	
32790	8016	Rx - Tx Leng	L
91	17		H
32792	8018	Rx - Tx Add	L
93	19		H
32794	801A	NeaT Add	L
95	1B	(Rx - Tx) Pgm IN	H
32796	801C	NeaT Add	L
97	1D	(Rx - Tx) bulk OUT	H
32798	801E	SWITCHES	
32799	801F	Analog Input	

DISPLAY MAP

8	7	6	5	4	3	2	1	0

RAM MAP

32800	8020	Analog VAR Port	
32801	8021	" Var.	
32802	8022	PP Var	L
03	23		H
32804	8024	Pgm Add in Execution	L
05	25	(PC)	H
32806	8026	Process "VAR"	L
02	27		H
32808	8028	Delay "CTE"	L
09	29		H
32810	802A	CALL &	CD 205
11	2B	RETURN	.. XX
12	2C	Rutine	.. XX
13	2D		C9 201
32814	802E	Vin time on Change	(L)
15	2F		(H)
32816	8030	V1 IN (VIN) CHECK IN RUTINE	
32912	8031	V2 Ent(VIN) CHECK IN RUTINE	
32818	8032	MOTOR * (VAR)	L
19	33		H
32820	8034	MOTOR * (VAR)	L
21	35		H
32822	8036	MOTOR * VAR	L
23	37		H
32824	8038	VAR (d) 1 :	
32825	8039	VAR (d) 2 :	
33024	8100	TABLA (DIONISOS)	
33279	81FF		
65535	FFFF	STACK	